

Tarago Action Plan Routine Inspection Checklist

Date: 8th December 2022	UGL RL Environmental Representative completing inspection ¹ :
Start time: 0800	
Finish time: 0930	
Weather: Clear, fine, Windy ~28km/h(W), 12 Degrees	
	BoM
Date and volume of maximum rainfall in a 24hr period since last inspection?	
Date: 22/11/2022	
Max volume (mm) in 24hr period: 1mm	
General Site Observations	
Is airborne dust from site evident? No. Despite wind strength of ~28km/h	
Is sediment run-off evident that is not captured by sediment controls? No. Controls compliant	
Is surface water discharging from site? Yes. Discharged outside of boundary fence, at Northern end of site, Boyd Street but pooled and not flowing nor crossed road.	
Is there evidence of excavation or other works non-compliant with the Action Plan?	
No.	
Other observations? Site is in good general condition. Ground cover vegetation off-corridor is established with good seasonal growth.	

¹Action Plan inspections must be completed by a UGL Representative suitably trained and experienced in application and management of erosion and sediment controls including stockpile management.

