Date: 7-11 - 22	UGL RL Environmental Representative completing inspection ¹ :		
Start time: C730			
Finish time:			
Weather: FINE Humid			
	Bo		
Date and volume of maximum rainfall in a 24 Date: $6+7-1/-2$ Max volume (mm) in 24hr period: 400 mg			
General Site Observations			
Is airborne dust from site evident?	No		
Is sediment run-off evident that is not captur	ed by sediment controls?		
Y	NO NO		
Is surface water discharging from site?	YES		
Is there evidence of excavation or other work	s non-compliant with the Action Plan?		
	0 (0)		
Other observations?	NO		
other observations.			

¹Action Plan inspections must be completed by a UGL Representative suitably trained and experienced in application and management of erosion and sediment controls including stockpile management.

Plan Ref	Control	Inspection		- Corrective Action	
			Yes	No	- Corrective Action
	recommen 1 to deman	n Zone signage present as ded on Figures 2a - 2e Appendix cate contamination in the rail and adjacent soils?	YÉS		
5.1	Is Exclusio	n Zone signage undamaged?	455		
	each rail co	ent controls present in/adjacent ulvert? t is present what is the depth of sediment?	YES Smil 3	P.B.	AVE
	Are sedime	nt controls still functional?	4ES		
7.3		ing stockpile covered securely surface water infiltration?	403		
	sediment relating to	igns of cracking, erosion, un-off or vegetation on or the existing stockpile? dditional stockpiles of		NO	
	contaminat Are addition drainage lininlets?	ed material been created? nal stockpiles placed away from nes, gutters, stormwater pits or		2/4	
	Surface wat Are stockpi	les covered securely to prevent er infiltration? les positioned on level surfaces uction of bunds to control water		N/A	

¹Action Plan inspections must be completed by a UGL Representative suitably trained and experienced in application and management of erosion and sediment controls including stockpile management.