

NEWCASTLE INNER CITY BYPASS: RANKIN PARK TO JESMOND
ENVIRONMENTAL REPRESENTATIVE MONTHLY REPORT

September 2019

Reporting Period: 1 to 30 September 2019

CONSTRUCTION SUMMARY: The construction project has been broken into stages:

Stage 1: Detailed design investigation and low impact works

Stage 2: Shared Path Bridge

Stage 3: Southern Utilities relocation works

Stage 4: Main RP2J road construction

No works have commenced. Pre-construction documentation has been under preparation and review by RMS, ER and DPIE. Daracon has been awarded the contract for construction of the Shared Path Bridge (Stage 2) and are scheduled to commence in October 2019.

September 2019 Completed Works:

Low Impact Works

- Work has not commenced.

Shared Path Bridge

- Work has not commenced.

October 2019 Upcoming Works:

Low Impact Works

- Work has not commenced.

Shared Path Bridge

- Work is scheduled to commence.

ER Activity:

Reviews/Approvals

The following table provides a list of preconstruction reports which have been prepared and reviewed by the ER.



Document	ER Reviewed	ER Certification Required	ER Certified
A9 - SPB CEMPP, Sub Plans and EWMS	Under review	Yes (approval)	No
A10 – Staging Report	Yes	No	
A15 – Ancillary Facility Management Plan (SPB)	Yes	No	
A29 – Compliance Monitoring and Reporting Program	Yes	Yes (endorsement)	Yes
A31 – Pre-construction Compliance Report	Yes	Yes (approval)	Yes
A34 – Independent Audit Program	Yes	No	
B3 – Community Consultation Strategy	Yes	No	
B7 – Complaints Management System	Yes	No	
B10 – Complaints Register	Yes	Yes (made available)	Yes
E15 – The Unexpected Heritage Finds and Human Remains Procedure	Yes	No	
E31 – Out Of Hours Work Protocol	Yes	Yes (consultation)	Yes
E59 – Unexpected Contaminated Land and Asbestos Finds Procedure	Yes	No	
E77 – Final Design of Bridge 7 & 8	Yes	No	

Inspections

- No inspections were held in September.

ERG

- ERGs will not be held for the Shared Path Bridge or Low Impact Works.

Audits

- There were no audits held in September.

Stop Work Notices

- None issued.

Incidents

- There were no incidents in September.



CEMP & Minister's Conditions of Approval

- CEMPP and subplans - Review.

Monitoring

- There was no monitoring undertaken in September 2019.

Community Consultation and Complaints

- There were no reportable matters in September 2019

Project Positives

- There were no project positives in September 2019



Simon Williams
NICB RP2J Environmental Representative
Director
GeoLINK

Attachments: [ER inspection reports are included in the monthly report]



Site Images – September (Site Visit on 3 October 2019)



Photo 1: View looking north east along McCaffrey Drive towards the project



Photo 2: Bush track behind houses on the western side of Lookout Road



Photo 4: Cleared and grassed area behind houses on the western side of Lookout Road. Houses to be demolished.



Photo 3: View looking south from bushland at the rear of houses along the western side of Lookout road.



Photo 5: View looking north at the intersection of McCaffery Drive and Lookout Road.



Photo 6: View looking south, just south of the intersection of McCaffery Drive and Lookout Road.

