


# A closer look at Jenolan Caves Road at Five Mile



# Steps to recovery of Jenolan Caves Road at Five Mile



Isolate area of collapsed road & prevent entry from people/traffic



Ongoing survey & investigation

WE ARE  
HERE



Environmental assessment



Geotechnical & construction design



Repair and reopen road

# Jenolan Caves Road at Five Mile

> The road is currently unsupported and the weight of traffic likely to cause further collapse

> Guardrail is suspended in mid-air, offering no restraint to errant vehicles

> There is continued erosion below the road - increasing the size of undermining and voiding (exacerbated due to wet weather)

> The ground below the road is steep and difficult to access making reinstatement very complex