



A closer look at Jenolan Caves Road at Hampton



Steps to recovery of Jenolan Caves Road at Hampton



Identify and isolate areas of affected walls to decrease risk of collapse



Ongoing survey & investigation

WE ARE
HERE



Assessment of temporary stabilisation measures



Environmental assessment



Geotechnical & construction design



Repair and reopen road

Jenolan Caves Road at Hampton

- The slope above the road has been repaired with significant scaling works to remove loose debris, install rock bolts and rock fall mesh
- On the slope below the road, some sections of retaining walls affected by erosion are exposed and hanging in mid-air offering no support to the road
- Continued erosion from wet weather below the road is increasing the size of the affected areas
- Traffic is not permitted over the affected areas to reduce the risk of road collapse
- Steep ground below the road makes repair and reinstatement very challenging