


Bombo Quarry

Location: Stn 'K'
Triggered by : Vector Sum

Date: 2025-07-29
Time: 10:59:45

Triggers Set : Vector Sum: 0.29mm/s, Channels 1-3: 0.28mm/s



RESULTS

Peak Vector Sum Velocity : 1.53 mm/s at 0.461 s
Peak Overpressure : 118.7 dBL at 1.329 s

	Peak	Frequency	Time	Acceleration	Displacement
	[mm/s]	(ZC at Peak) [Hz]	(Rel. to Trigger) [s]	(Est. from PPV) [mm/s ²]	(Est. from PPV) [mm]
Radial	1.01	14.0	0.730	34	18.0
Transverse	1.39	23.7	0.515	116	14.7
Vertical	1.44	16.6	0.447	69	21.7

Monitoring conducted by:
(Your Company Name:Your Name)

TM Serial Number : 4422 Last Calibration: 2025-07-16

Bombo Quarry\M4422 Bombo Quarry @ Stn 'K' @ 2025-07-29 10.59.45.twf
T-Link 1.2 - ANZEC Standard.rtt


Texcel Monitors comply with Appendix J of AS 2187.2-2006

Bombo Quarry

Location: Stn 'K'
Triggered by : Vector Sum

Date: 2025-07-29
Time: 10:59:45

Triggers Set : Vector Sum: 0.29mm/s, Channels 1-3: 0.28mm/s



RESULTS

Peak Vector Sum Velocity : 1.53 mm/s at 0.461 s
Peak Overpressure : 118.7 dBL at 1.329 s

	Peak	Frequency	Time	Acceleration	Displacement
	[mm/s]	(ZC at Peak) [Hz]	(Rel. to Trigger) [s]	(Est. from PPV) [mm/s ²]	(Est. from PPV) [mm]
Radial	1.01	14.0	0.730	34	18.0
Transverse	1.39	23.7	0.515	116	14.7
Vertical	1.44	16.6	0.447	69	21.7

Monitoring conducted by:
(Your Company Name:Your Name)

TM Serial Number : 4422 Last Calibration: 2025-07-16

Bombo Quarry\M4422 Bombo Quarry @ Stn 'K' @ 2025-07-29 10.59.45.twf
T-Link 1.2 - ANZEC Standard.rtt


Texcel Monitors comply with Appendix J of AS 2187.2-2006

Bombo Quarry

Location: Stn 'K'
Triggered by : Vector Sum

Date: 2025-07-29
Time: 10:59:45

Triggers Set : Vector Sum: 0.29mm/s, Channels 1-3: 0.28mm/s



RESULTS

Peak Vector Sum Velocity : 1.53 mm/s at 0.461 s
Peak Overpressure : 118.7 dBL at 1.329 s

	Peak	Frequency	Time	Acceleration	Displacement
	[mm/s]	(ZC at Peak) [Hz]	(Rel. to Trigger) [s]	(Est. from PPV) [mm/s ²]	(Est. from PPV) [mm]
Radial	1.01	14.0	0.730	34	18.0
Transverse	1.39	23.7	0.515	116	14.7
Vertical	1.44	16.6	0.447	69	21.7

Monitoring conducted by:
(Your Company Name:Your Name)

TM Serial Number : 4422 Last Calibration: 2025-07-16

Bombo Quarry\M4422 Bombo Quarry @ Stn 'K' @ 2025-07-29 10.59.45.twf
T-Link 1.2 - ANZEC Standard.rtt

Texcel Monitors comply with Appendix J of AS 2187.2-2006