

1

# NEWCASTLE INNER CITY BYPASS: RANKIN PARK TO JESMOND ENVIRONMENTAL REPRESENTATIVE MONTHLY REPORT October 2019

Reporting Period: 1 to 31 October 2019

**CONSTRUCTION SUMMARY:** The NICB RP2J construction project has been broken into stages: Stage 1: Detailed design investigation and low impact works Stage 2: Share Path Bridge Stage 3: Southern Utilities relocation works Stage 4: Main RP2J road construction

No works have commenced. Pre-construction documentation has been under preparation and review by RMS, ER and DPIE. Daracon has been awarded the contract for construction of the Shared Path Bridge (Stage 2) and are scheduled to commence in November 2019.

# October 2019 Completed Works:

## Low Impact Works

Work has not commenced.

#### Shared Path Bridge

• Work has not commenced.

# November 2019 Upcoming Works:

#### Low Impact Works

Work has not commenced.

#### Shared Path Bridge

• Work is scheduled to commence.

# ER Activity:

# **Reviews/Approvals**





Provision of advice on Ancillary Facility establishment and approval of one new Ancillary Facility and an increase in size of an existing EIS approved Ancillary Facility.

Document	ER Reviewed	ER Certification Required	ER Certified
A9 - SPB CEMPP, Sub Plans and EWMS	Under	Yes	No
	review	(approval)	
A10 – Staging Report	Yes	No	N/A
A15 – Ancillary Facility Establishment Management Plan (SPB)	Under review	Yes	No
A29 – Compliance Monitoring and Reporting Program	Yes	Yes (endorsement)	Yes
A31 – Pre-construction Compliance Report	Yes	Yes	Yes
		(approval)	
A34 – Independent Audit Program	Yes	No	N/A
B3 – Community Consultation Strategy	Yes	No	N/A
B7 – Complaints Management System	Yes	No	N/A
B10 – Complaints Register	Yes	Yes	Yes
		(made available)	
E15 – The Unexpected Heritage Finds and Human Remains Procedure	Yes	No	N/A
E31 – Out Of Hours Work Protocol	Yes	Yes	Yes
		(consultation)	
E59 – Unexpected Contaminated Land and Asbestos Finds Procedure	Yes	No	N/A
E77 – Final Design of Bridge 7 & 8	Yes	No	N/A

#### Inspections

• A meeting and inspection were undertaken on the 3<sup>rd</sup> October 2019 with DPIE and RMS.

## ERG

ERGs will not be held for the Shared Path Bridge or Low Impact Works.





3

## Audits

• There were no audits held in October.

#### **Stop Work Notices**

None issued.

## Incidents

There were no incidents in October.

## **CEMP & Minister's Conditions of Approval**

- MCoA A9 (SPB) CEMPP and subplans Reviewing
- MCoA A15 (SPB) Ancillary Facility Establishment Management Plan Reviewing

# Monitoring

There was no monitoring undertaken in October 2019.

# **Community Consultation and Complaints**

There were no reportable matters in October 2019

# **Project Positives**

There were no project positives in October 2019

Simon Williams NICB RP2J Environmental Representative Director GeoLINK

Attachments: [ER inspection reports will be included in the monthly report]

3291-1006



Site Images – September (Site Visit on 3 October 2019)





Photo 1: View looking north east along McCaffrey Drive towards the project



Photo 4: Cleared and grassed area behind houses on the western side of Lookout Road. Houses to be demolished.

Photo 2: Bush track behind houses on the western side of Lookout Road



Photo 3: View looking south from bushland at the rear of houses along the western side of Lookout road.



Photo 5: View looking north at the intersection of McCaffery Drive and Lookout Road.



Photo 6: View looking south, just south of the intersection of McCaffery Drive and Lookout Road.



4