

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R669
Client: Georgiou
Client Address: Level 3,
 53 Berry Street,
 North Sydney, NSW, 2060

Report Date: Thursday, 4 April 2024
Analysed Date: Thursday, 4 April 2024
Laboratory Receival Date: Thursday, 4 April 2024
Sampled Date: Monday, 1 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Approved Counter and Signatory: [REDACTED]

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9402	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9403	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9404	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9405	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9406	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9407	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9408	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9409	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9410	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9411	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9412	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9413	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9414	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9415	158 Goldrush Road South/East Gate	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9416	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9417	Cut 3 Reedsdale Road South/East Fence	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9418	Reedsdale Road & Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9419	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9420	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9421	Lot 1 Bogan Road - West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9422	Lot 1 Bogan Road - North/West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9423	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R670	Report Date: Thursday, 4 April 2024
Client: Georgiou	Analysed Date: Thursday, 4 April 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Thursday, 4 April 2024
	Sampled Date: Tuesday, 2 April 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parkes Bypass Project	Type of Monitoring: Background Monitoring During Earthworks
Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.	

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9424	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9425	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9426	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9427	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9428	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9429	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9430	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9431	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9432	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9433	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9434	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9435	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9436	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9437	158 Goldrush Road South/East Gate	1159	1200 1440 min	0.5	2/100	< 0.01
A27251-S9438	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9439	Cut 3 Reedsdale Road South/East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9440	Reedsdale Road & Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9441	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9442	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9443	Lot 1 - Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9444	Lot 1 - Bogan Road North/West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9445	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R671

Client: Georgiou

Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Monday, 8 April 2024

Analysed Date: Friday, 5 April 2024

Laboratory Receival Date: Friday, 5 April 2024

Sampled Date: Wednesday, 3 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9446	London Road South	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9447	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9448	Ballardee Lane South/west	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9449	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9450	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9451	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9452	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9453	Hartigan Avenue East	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9454	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9455	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9456	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9457	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9458	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9459	158 Goldrush Road South/East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9460	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9461	Cut 3 Reedsdale Road South/East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9462	Reedsdale Road & Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9463	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9464	125 Painters Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9465	Lot 1 Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9466	Lot 1 Bogan Road North/ West Fence	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9467	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R672	Report Date: Monday, 8 April 2024
Client: Georgiou	Analysed Date: Monday, 8 April 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Monday, 8 April 2024
	Sampled Date: Thursday, 4 April 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parkes Bypass Project	Type of Monitoring: Background Monitoring During Earthworks
Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.	

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9468	London Road South	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9469	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9470	Ballardee Lane South/West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9471	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9472	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9473	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9474	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9475	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9476	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9477	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9478	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9479	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9480	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9481	158 Goldrush Road South/East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9482	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9483	Cut 3 Reedsdale Road South/East fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9484	Reedsdale Road & Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9485	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9486	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9487	Lot 1 - Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9488	Lot 1 - Bogan Road North/West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9489	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT Estimation of Airborne Asbestos Fibres

Report No: A27251-R673
Client: Georgiou
Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Tuesday, 9 April 2024
Analysed Date: Monday, 8 April 2024
Laboratory Receival Date: Monday, 8 April 2024
Sampled Date: Friday, 5 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Approved Counter and Signatory: [REDACTED]

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9490	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9491	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9492	Ballardee Lane South/West	1159	1200 1440 min	0.5	3/100	< 0.01
A27251-S9493	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9494	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9495	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9496	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9497	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9498	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9499	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9500	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9501	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9502	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9503	158 Goldrush Road South/East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9504	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9505	Cut 3 Reedsdale Road South/East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9506	Reedsdale Road & Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9507	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9508	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9509	Lot 1 Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9510	Lot 1 Bogan Road North/West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9511	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R674

Client: Georgiou

Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Tuesday, 9 April 2024

Analysed Date: Monday, 8 April 2024

Laboratory Receival Date: Monday, 8 April 2024

Sampled Date: Saturday, 6 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During
Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9512	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9513	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9514	Ballardee Lane South/West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9515	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9516	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9517	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9518	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9519	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9520	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9521	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9522	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9523	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9524	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9525	158 Goldrush Road South/East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9526	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9527	Cut 3 Reedsdale Road South/East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9528	Reedsdale Road & Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9529	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9530	125 Painters Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9531	Lot 1 - Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9532	Lot 1 - Bogan Road North/West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9533	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R675
Client: Georgiou
Client Address: Level 3,
 53 Berry Street,
 North Sydney, NSW, 2060

Report Date: Tuesday, 9 April 2024
Analysed Date: Tuesday, 9 April 2024
Laboratory Receival Date: Tuesday, 9 April 2024
Sampled Date: Sunday, 7 April 2024

Sampled By: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9534	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9535	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9536	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9537	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9538	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9539	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9540	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9541	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9542	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9543	Cut 3 Moulden Street South	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9544	Cut 3 Moulden Street North	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9545	Fill 4 Moulden Street	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9546	Cut 3 Moulden Street West	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9547	158 GoldRush Road South East Gate	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9548	163 GoldRush Road	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9549	Cut 3 Reedsdale Road South East Fence	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9550	Reedsdale Road and Thomas Street	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9551	Fill 4 Reedsdale Road	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9552	125 Painter Street	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9553	LOT 1 Bogan Road West Fence	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9554	LOT 1 Bogan Road North West Fence	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9555	Quality Control Laboratory Blank	1159	1200 / 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R676
Client: Georgiou
Client Address: Level 3,
 53 Berry Street,
 North Sydney, NSW, 2060

Report Date: Thursday, 11 April 2024
Analysed Date: Wednesday, 10 April 2024
Laboratory Receival Date: Wednesday, 10 April 2024
Sampled Date: Monday, 8 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Approved Counter and Signatory: [REDACTED]

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9556	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9557	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9558	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9559	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9560	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9561	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9562	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9563	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9564	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9565	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9566	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9567	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9568	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9569	158 Goldrush Road South East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9570	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9571	Cut 3 Reedsdale Road South East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9572	Reedsdale Road and Thomas Street	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9573	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9574	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9575	LOT 1 Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9576	LOT 1 Bogan Road North West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9577	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R677

Client: Georgiou

Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Thursday, April 11, 2024

Analysed Date: Thursday, April 11, 2024

Laboratory Receival Date: Thursday, April 11, 2024

Sampled Date: Tuesday, April 9, 2024

Sampled By: [REDACTED]

Attention: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During
Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9578	London Road South	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9579	London Road North	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9580	Ballarde Lane South/West	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9581	Ballarde Lane North	1159	1200 1440 min	0.5	1 /100	< 0.01
A27251-S9582	Brolgan Road West	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9583	Brolgan Road East	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9584	Hartigan Avenue West	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9585	Hartigan Avenue East	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9586	Hartigan Avenue North	1159	1200 1440 min	0.5	0 /100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9587	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9588	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9589	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9590	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9591	158 Goldrush Road South/East Gate	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9592	163 Goldrush Road	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9593	Cut 3 Reedsdale Road South/East Fence	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9594	Reedsdale Road & Thomas Street	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9595	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9596	125 Painters Street	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9597	Lot 1 Bogan Road West Fence	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9598	Lot 1 Bogan Road North/West Fence	1159	1200 1440 min	0.5	0 /100	< 0.01
A27251-S9599	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0 /100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R678	Report Date: Friday, 12 April 2024
Client: Georgiou	Analysed Date: Friday, 12 April 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Friday, 12 April 2024
	Sampled Date: Wednesday, 10 April 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parkes Bypass Project	Type of Monitoring: Background Monitoring During Earthworks
Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.	

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9600	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9601	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9602	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9603	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9604	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9605	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9606	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9607	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9608	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9609	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9610	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9611	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9612	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9613	158 Goldrush Road South East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9614	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9615	Cut 3 Reedsdale Road South East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9616	Reedsdale Road and Thomas Street	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9617	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9618	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9619	LOT 1 Bogan Road West Fence	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9620	LOT 1 Bogan Road North West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9621	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R679
Client: Georgiou
Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Monday, 15 April 2024
Analysed Date: Monday, 15 April 2024
Laboratory Receival Date: Monday, 15 April 2024
Sampled Date: Thursday, 11 April 2024

Sampled By: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9622	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9623	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9624	Ballardee Lane South/West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9625	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9626	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9627	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9628	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9629	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9630	Hartigan Avenue North	1159	1200 1440 min	0.5	2/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9631	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9632	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9633	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9634	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9635	158 Goldrush Road South/East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9636	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9637	Cut 3 Reedsdale Road South/East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9638	Reedsdale Road & Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9639	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9640	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9641	Lot 1 Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9642	Lot 1 Bogan Road North/West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9643	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT Estimation of Airborne Asbestos Fibres

Report No: A27251-R680	Report Date: Monday, 15 April 2024
Client: Georgiou	Analysed Date: Monday, 15 April 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Monday, 15 April 2024
	Sampled Date: Friday, 12 April 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parkes Bypass Project	Type of Monitoring: Background Monitoring During Earthworks
Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.	

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9644	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9645	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9646	Ballardee Lane South/West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9647	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9648	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9649	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9650	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9651	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9652	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9653	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9654	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9655	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9656	Cut 3 Mouldne Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9657	158 Goldrush Road South/East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9658	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9659	Cut 3 Reedsdale Road South/East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9660	Reedsdale Road & Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9661	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9662	125 Painters Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9663	Lot 1 - Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9664	Lot 1 - Bogan Road North/West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9665	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R681	Report Date: Tuesday, 16 April 2024
Client: Georgiou	Analysed Date: Monday, 15 April 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Monday, 15 April 2024
	Sampled Date: Saturday, 13 April 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parkes Bypass Project	Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9666	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9667	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9668	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9669	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9670	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9671	Brolgan Road East	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9672	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9673	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9674	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9675	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9676	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9677	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9678	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9679	158 Goldrush Road South East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9680	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9681	Cut 3 Reedsdale Road South East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9682	Reedsdale Road and Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9683	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9684	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9685	LOT 1 Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9686	LOT 1 Bogan Road North West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9687	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R682
Client: Georgiou
Client Address: Level 3,
 53 Berry Street,
 North Sydney, NSW, 2060

Report Date: Tuesday, 16 April 2024
Analysed Date: Tuesday, 16 April 2024
Laboratory Receival Date: Tuesday, 16 April 2024
Sampled Date: Sunday, 14 April 2024

Sampled By: [REDACTED]
Approved Counter and Signatory: [REDACTED]
Attention: [REDACTED]
Sampled From: Parkes Bypass Project
Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9688	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9689	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9690	Ballardee Lane South West	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9691	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9692	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9693	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01 —
A27251-S9694	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9695	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9696	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9697	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9698	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9699	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9700	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9701	158 Goldrush Road South East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9702	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9703	Cut 3 Reedsdale Road South East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9704	Reedsdale Road and Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9705	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9706	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9707	LOT 1 - Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9708	LOT 1 - Bogan Road North West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9709	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R683
Client: Georgiou
Client Address: Level 3,
 53 Berry Street,
 North Sydney, NSW, 2060

Report Date: Wednesday, 17 April 2024
Analysed Date: Wednesday, 17 April 2024
Laboratory Receival Date: Wednesday, 17 April 2024
Sampled Date: Monday, 15 April 2024

Sampled By: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9710	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9711	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9712	Ballardee Lane South/West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9713	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9714	Brolgan Road west	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9715	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9716	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9717	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9718	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9719	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9720	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9721	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9722	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9723	158 Goldrush Road South/East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9724	163 Goldrush Road	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9725	Cut 3 Reedsdale Road South/East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9726	Reedsdale Road & Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9727	Fill 4 Reedsdae Road	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9728	125 Painters Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9729	Lot 1 Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9730	Lot 1 Bogan Road North West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9731	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R684
Client: Georgiou
Client Address: Level 3,
 53 Berry Street,
 North Sydney, NSW, 2060

Report Date: Thursday, 18 April 2024
Analysed Date: Thursday, 18 April 2024
Laboratory Receival Date: Thursday, 18 April 2024
Sampled Date: Tuesday, 16 April 2024

Sampled By: [REDACTED]
Approved Counter and Signatory: [REDACTED]
Attention: [REDACTED]
Sampled From: Parkes Bypass Project
Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9732	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9733	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9734	Ballardee Lane South/West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9735	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9736	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9737	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9738	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9739	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9740	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9741	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9742	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9743	Fill 4 Moulden street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9744	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9745	158 Goldrush Road South East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9746	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9747	Cut 3 Reedsdale Road South East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9748	Reedsdale Road and Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9749	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9750	125 PainterStreet	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9751	LOT 1 - Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9752	LOT 1 - Bogan Road NorthWest Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9753	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R685	Report Date: Friday, 19 April 2024
Client: Georgiou	Analysed Date: Friday, 19 April 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Friday, 19 April 2024
	Sampled Date: Wednesday, 17 April 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parkes Bypass Project	Type of Monitoring: Background Monitoring During Earthworks
Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.	

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9754	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9755	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9756	Ballardee Lane South/West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9757	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9758	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9759	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9760	Hartigan Aenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9761	Hartigan Aenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9762	Hartigan Aenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9763	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9764	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9765	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9766	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9767	158 Goldrush Road South/East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9768	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9769	Cut 3 Reedsdale Road South/East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9770	Reedsdale Road & Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9771	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9772	125 Painters Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9773	LOT 1 - Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9774	LOT 1 - Bogan Road North/West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9775	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R686
Client: Georgiou
Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Monday, 22 April 2024
Analysed Date: Monday, 22 April 2024
Laboratory Receival Date: Monday, 22 April 2024
Sampled Date: Thursday, 18 April 2024

Sampled By: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9776	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9777	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9778	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9779	Ballardee Lane North	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9780	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9781	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9782	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9783	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9784	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9785	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9786	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9787	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9788	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9789	158 Goldrush Road South East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9790	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9791	Cut 3 Reedsdale Road South East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9792	Reedsdale Road and Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9793	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9794	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9795	LOT 1 - Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9796	LOT 1 - Bogan Road North West Fence	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9797	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R687	Report Date: Monday, 22 April 2024
Client: Georgiou	Analysed Date: Monday, 22 April 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Monday, 22 April 2024
	Sampled Date: Friday, 19 April 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parkes Bypass Project	Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9798	London Road South	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9799	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9800	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9801	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9802	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9803	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9804	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9805	Hartigan Avenue East	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9806	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9807	Cut 3 Moulden Street South	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9808	Cut 3 Moulden Street North	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9809	Fill 4 Moulden Street	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9810	Cut 3 Moulden Street West	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9811	158 Goldrush Road South East Gate	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9812	163 Goldrush Road	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9813	Cut 3 Reedsdale Road South East Fence	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9814	Reedsdale Road and Thomas Street	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9815	Fill 4 Reedsdale Road	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9816	125 painter Street	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9817	LOT 1 - Bogan Road West Fence	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9818	LOT 1 - Bogan Road North West Fence	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9819	Quality Control Laboratory Blank	1159	1200 / 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R688
Client: Georgiou
Client Address: Level 3,
 53 Berry Street,
 North Sydney, NSW, 2060

Report Date: Wednesday, 24 April 2024
Analysed Date: Wednesday, 24 April 2024
Laboratory Receival Date: Wednesday, 24 April 2024
Sampled Date: Saturday, 20 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Approved Counter and Signatory: [REDACTED]

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9820	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9821	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9822	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9823	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9824	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9825	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9826	Hartigan Avenue West	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9827	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9828	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9829	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9830	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9831	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9832	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9833	158 Goldrush Road South East Gate	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9834	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9835	Cut 3 Reedsdale Road South East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9836	Reedsdale Road and Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9837	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9838	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9839	LOT 1 - Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9840	LOT 1 - Bogan Road North West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9841	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT Estimation of Airborne Asbestos Fibres

Report No: A27251-R689
Client: Georgiou
Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Wednesday, 24 April 2024
Analysed Date: Wednesday, 24 April 2024
Laboratory Receival Date: Wednesday, 24 April 2024
Sampled Date: Sunday, 21 April 2024

Sampled By: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9842	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9843	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9844	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9845	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9846	Brogan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9847	Brogan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9848	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9849	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9850	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9851	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9852	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9853	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9854	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9855	158 Goldrush Road South East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9856	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9857	Cut 3 Reedsdale Road South East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9858	Reedsdale Road and Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9859	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9860	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9861	LOT 1 Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9862	LOT 1 Bogan Road North West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9863	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R690

Client: Georgiou

Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Friday, 26 April 2024

Analysed Date: Wednesday, 24 April 2024

Laboratory Receival Date: Wednesday, 24 April 2024

Sampled Date: Monday, 22 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9864	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9865	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9866	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9867	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9868	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9869	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9870	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9871	Hartigan Avenue East	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9872	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9873	Cut 3 Moulden Street South	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9874	Cut 3 Moulden Street North	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9875	Fill 4 Moulden Street	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9876	Cut 3 Moulden Street West	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9877	158 Goldrush Road South East Gate	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9878	163 Goldrush Road	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9879	Cut 3 Reedsdale Road South East Fence	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9880	Reedsdale Road and Thomas Street	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9881	Fill 4 Reedsdale Road	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9882	125 Painter Street	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9883	LOT 1 Bogan Road West Fence	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9884	LOT 1 Bogan Road North West Fence	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9885	Quality Control Laboratory Blank	1159	1200 / 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R691

Client: Georgiou

Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Friday, 26 April 2024

Analysed Date: Friday, 26 April 2024

Laboratory Receival Date: Friday, 26 April 2024

Sampled Date: Tuesday, 23 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During
Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9886	London Road South	1159	1200 1440 min	0.5	1/100	< 0.01
A27251-S9887	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9888	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9889	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9890	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9891	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9892	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9893	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9894	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9895	Cut 3 Moulden Street South	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9896	Cut 3 Moulden Street North	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9897	Fill 4 Moulden Street	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9898	Cut 3 Moulden Street West	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9899	158 Goldrush Road South East Gate	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9900	163 Goldrush Road	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9901	Cut 3 Reedsdale Road South East Fence	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9902	Reedsdale Road and Thomas Street	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9903	Fill 4 Reedsdale Road	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9904	125 Painter Street	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9905	LOT 1 - Bogan Road West Fence	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9906	LOT 1 - Bogan Road North West Fence	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9907	Quality Control Laboratory Blank	1159	1200 / 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27251-R692	Report Date: Tuesday, 30 April 2024
Client: Georgiou	Analysed Date: Monday, 29 April 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Monday, 29 April 2024
	Sampled Date: Wednesday, 24 April 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parkes Bypass Project	Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9908	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9909	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9910	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9911	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9912	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9913	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9914	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9915	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9916	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9917	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9918	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9919	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9920	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9921	158 Goldrush Road South East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9922	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9923	Cut 3 Reedsdale Road South East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9924	Reedsdale Road and Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9925	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9926	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9927	LOT 1 - Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9928	LOT 1 - Bogan Road North West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9929	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT Estimation of Airborne Asbestos Fibres

Report No: A27251-R693
Client: Georgiou
Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Tuesday, 30 April 2024
Analysed Date: Monday, 29 April 2024
Laboratory Receival Date: Monday, 29 April 2024
Sampled Date: Thursday, 25 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Approved Counter and Signatory: [REDACTED]

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9930	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9931	London Road North	1159	1200 1440 min	0.5	2/100	< 0.01
A27251-S9932	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9933	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9934	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9935	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9936	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9937	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9938	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9939	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9940	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9941	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9942	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9943	158 Goldrush Road South East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9944	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9945	Cut 3 Reedsdale Road South East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9946	Reedsdale Road and Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9947	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9948	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9949	LOT 1 - Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9950	LOT 1 - Bogan Road North West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9951	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT Estimation of Airborne Asbestos Fibres

Report No: A27251-R694	Report Date: Wednesday, 1 May 2024
Client: Georgiou	Analysed Date: Tuesday, 30 April 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Tuesday, 30 April 2024
	Sampled Date: Friday, 26 April 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parkes Bypass Project	Type of Monitoring: Background Monitoring During Earthworks
Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.	

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9952	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9953	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9954	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9955	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9956	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9957	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9958	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9959	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9960	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9961	Cut 3 Moulden Street South	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9962	Cut 3 Moulden Street North	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9963	Fill 4 Moulden Street	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9964	Cut 3 Moulden Street West	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9965	158 Goldrush Road South East Gate	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9966	163 Goldrush Road	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9967	Cut 3 Reedsdale Road South East Fence	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9968	Reedsdale Road and Thomas Street	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9969	Fill 4 Reedsdale Road	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9970	125 Painter Street	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9971	LOT - 1 - Bogan Road West Fence	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9972	LOT - 1 - Bogan Road North West Fence	1159	1200 / 1440 min	0.5	0/100	< 0.01
A27251-S9973	Quality Control Laboratory Blank	1159	1200 / 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT
Estimation of Airborne Asbestos Fibres

Report No: A27251-R695

Client: Georgiou

Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Wednesday, 1 May 2024

Analysed Date: Tuesday, 30 April 2024

Laboratory Receival Date: Tuesday, 30 April 2024

Sampled Date: Saturday, 27 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During
Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9974	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9975	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9976	Ballardee Lane South West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9977	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9978	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9979	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9980	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9981	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9982	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27251-S9983	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9984	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9985	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9986	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9987	158 Goldrush Road South East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9988	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9989	Cut 3 Reedsdale Road South East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9990	Reedsdale Road and Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9991	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9992	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9993	LOT-1- Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9994	LOT-1- Bogan Road North West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A27251-S9995	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R432
Client: Georgiou
Client Address: Level 3,
 53 Berry Street,
 North Sydney, NSW, 2060

Report Date: Thursday, 4 April 2024
Analysed Date: Thursday, 4 April 2024
Laboratory Receival Date: Thursday, 4 April 2024
Sampled Date: Tuesday, 2 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Approved Counter and Signatory: [REDACTED]

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4078	Gate 14 Crib Room	700	1500 480 min	1.0	1/100	< 0.01
A27351-S4079	Gate 14 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4080	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4081	Fill 5 Wheel Wash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4082	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4083	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4084	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4085	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4086	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4087	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4088	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4089	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4090	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R433

Client: Georgiou

Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Friday, 5 April 2024

Analysed Date: Friday, 5 April 2024

Laboratory Receival Date: Friday, 5 April 2024

Sampled Date: Wednesday, 3 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During
Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4091	Gate 14 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4092	Gate 14 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4093	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4094	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4095	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4096	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4097	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4098	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4099	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4100	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4101	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4102	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4103	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R434

Client: Georgiou

Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Monday, 8 April 2024

Analysed Date: Monday, 8 April 2024

Laboratory Receival Date: Monday, 8 April 2024

Sampled Date: Thursday, 4 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During
Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4104	Gate 14 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4105	Gate 14 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4106	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4107	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4108	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4109	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4110	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4111	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4112	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4113	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4114	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4115	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4116	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R435

Client: Georgiou

Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Tuesday, 9 April 2024

Analysed Date: Monday, 8 April 2024

Laboratory Receival Date: Monday, 8 April 2024

Sampled Date: Friday, 5 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4117	Gate 14 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4118	Gate 14 Clean End Decon	700	1500 480 min	1.0	1/100	< 0.01
A27351-S4119	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4120	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4121	Cut 3 West fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4122	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4123	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4124	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4125	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4126	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4127	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4128	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4129	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT Estimation of Airborne Asbestos Fibres

Report No: A27351-R436
Client: Georgiou
Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Tuesday, 9 April 2024
Analysed Date: Tuesday, 9 April 2024
Laboratory Receival Date: Tuesday, 9 April 2024
Sampled Date: Monday, 8 April 2024

Sampled By: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4130	Gate 14 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4131	Gate 14 Clean End Decon	700	1500 480 min	1.0	1/100	< 0.01
A27351-S4132	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4133	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4134	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4135	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4136	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4137	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4138	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4139	Reedsdale Road North Adjacent Conatinment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4140	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4141	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4142	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R437 Client: Georgiou Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060 Attention: XXXXXXXXXX Sampled From: Parkes Bypass Project	Report Date: Thursday, April 11, 2024 Analysed Date: Thursday, April 11, 2024 Laboratory Receival Date: Thursday, April 11, 2024 Sampled Date: Tuesday, April 9, 2024 Sampled By: XXXXXXXXXX Approved Counter and Signatory: XXXXXXXXXX Type of Monitoring: Background Monitoring During Earthworks
--	--

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4143	Gate 14 Crib Room	700	1500 480 min	1.0	1 /100	< 0.01
A27351-S4144	Gate 14 Clean End Decon	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4145	Gate 10 Fence	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4146	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4147	Cut 3 West Fence	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4148	Cut 3 Condobolin Road	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4149	Cut 3 East Fence	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4150	Brolgan Road East	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4151	Brolgan Road West	700	1500 480 min	1.0	0 /100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4152	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4153	Gate 8 Clean End Decon	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4154	Gate 8 Crib Room	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4155	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0 /100	Acceptable limit

LABORATORY ANALYSIS REPORT Estimation of Airborne Asbestos Fibres

Report No: A27351-R438	Report Date: Monday, 15 April 2024
Client: Georgiou	Analysed Date: Friday, 12 April 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Friday, 12 April 2024
	Sampled Date: Wednesday, 10 April 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parkes Bypass Project	Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4156	Gate 14 - Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4157	Gate 14 - Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4158	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4159	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4160	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4161	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4162	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4163	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4164	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4165	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4166	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4167	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4168	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R439

Client: Georgiou

Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Monday, 15 April 2024

Analysed Date: Friday, 12 April 2024

Laboratory Receival Date: Friday, 12 April 2024

Sampled Date: Thursday, 11 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4169	Gate 14 - Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4170	Gate 14 - Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4171	Gate 10 Fence	700	1500 480 min	1.0	1/100	< 0.01
A27351-S4172	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4173	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4174	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4175	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4176	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4177	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4178	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4179	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4180	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4181	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R440
Client: Georgiou
Client Address: Level 3,
 53 Berry Street,
 North Sydney, NSW, 2060

Report Date: Monday, 15 April 2024
Analysed Date: Monday, 15 April 2024
Laboratory Receival Date: Monday, 15 April 2024
Sampled Date: Friday, 12 April 2024

Sampled By: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4182	Gate 14 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4183	Gate 14 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4184	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4185	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4186	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4187	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4188	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4189	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4190	Brolgan Road West	700	1500 480 min	1.0	2/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4191	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4192	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4193	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4194	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT Estimation of Airborne Asbestos Fibres

Report No: A27351-R441	Report Date: Tuesday, 16 April 2024
Client: Georgiou	Analysed Date: Monday, 15 April 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Monday, 15 April 2024
	Sampled Date: Saturday, 13 April 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parkes Bypass Project	Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4195	Gate 14 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4196	Gate 14 Clean end Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4197	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4198	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4199	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4200	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4201	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4202	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4203	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4204	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4205	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4206	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4207	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R442

Client: Georgiou

Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Tuesday, 16 April 2024

Analysed Date: Tuesday, 16 April 2024

Laboratory Receival Date: Tuesday, 16 April 2024

Sampled Date: Monday, 15 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4208	Gate 14 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4209	Gate 14 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4210	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4211	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4212	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4213	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4214	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4215	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4216	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4217	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4218	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4219	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4220	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R443
Client: Georgiou
Client Address: Level 3,
 53 Berry Street,
 North Sydney, NSW, 2060

Report Date: Wednesday, 17 April 2024
Analysed Date: Wednesday, 17 April 2024
Laboratory Receival Date: Wednesday, 17 April 2024
Sampled Date: Tuesday, 16 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Approved Counter and Signatory: [REDACTED]

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4221	Gate 14 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4222	Gate 14 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4223	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4224	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4225	Cut 3 West Fence	700	1500 480 min	1.0	2/100	< 0.01
A27351-S4226	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4227	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4228	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4229	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4230	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4231	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4232	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4233	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R444	Report Date: Friday, 19 April 2024
Client: Georgiou	Analysed Date: Friday, 19 April 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Friday, 19 April 2024
	Sampled Date: Wednesday, 17 April 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parkes Bypass Project	Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4234	Gate 14 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4235	Gate 14 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4236	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4237	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4238	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4239	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4240	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4241	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4242	Brolgan Road West	700	1500 480 min	1.0	1/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4243	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4244	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4245	Gate 8 Crib Room	700	1500 480 min	1.0	1/100	< 0.01
A27351-S4246	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R445	Report Date: Monday, 22 April 2024
Client: Georgiou	Analysed Date: Monday, 22 April 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Monday, 22 April 2024
	Sampled Date: Thursday, 18 April 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parkes Bypass Project	Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4247	Gate 14 Crib Room	700	1500 480 min	1.0	1/100	< 0.01
A27351-S4248	Gate 14 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4249	Gate 10 Fence	700	1500 480 min	1.0	1/100	< 0.01
A27351-S4250	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4251	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4252	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4253	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4254	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4255	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4256	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4257	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4258	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4259	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R446
Client: Georgiou
Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Monday, 22 April 2024
Analysed Date: Monday, 22 April 2024
Laboratory Receival Date: Monday, 22 April 2024
Sampled Date: Friday, 19 April 2024

Sampled By: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4260	Gate 14 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4261	Gate 14 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4262	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4263	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4264	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4265	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4266	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4267	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4268	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4269	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4270	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4271	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4272	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R447
Client: Georgiou
Client Address: Level 3,
 53 Berry Street,
 North Sydney, NSW, 2060

Report Date: Wednesday, 24 April 2024
Analysed Date: Wednesday, 24 April 2024
Laboratory Receival Date: Wednesday, 24 April 2024
Sampled Date: Saturday, 20 April 2024

Sampled By: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4273	Gate 14 Crib Room	700	1500 480 min	1.0	2 /100	< 0.01
A27351-S4274	Gate 14 Clean End Decon	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4275	Gate 10 Fence	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4276	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	1 /100	< 0.01
A27351-S4277	Cut 3 West Fence	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4278	Cut 3 Condobolin Road	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4279	Cut 3 East Fence	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4280	Brolgan Road East	700	1500 480 min	1.0	0 /100	< 0.01
A27351-S4281	Brolgan Road West	700	1500 480 min	1.0	0 /100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4282	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4283	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4284	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4285	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R448
Client: Georgiou
Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Wednesday, 24 April 2024
Analysed Date: Wednesday, 24 April 2024
Laboratory Receival Date: Wednesday, 24 April 2024
Sampled Date: Monday, 22 April 2024

Sampled By: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4286	Gate 14 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4287	Gate 14 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4288	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4289	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4290	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4291	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4292	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4293	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4294	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4295	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4296	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4297	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4298	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R449
Client: Georgiou
Client Address: Level 3,
 53 Berry Street,
 North Sydney, NSW, 2060

Report Date: Friday, 26 April 2024
Analysed Date: Friday, 26 April 2024
Laboratory Receival Date: Friday, 26 April 2024
Sampled Date: Tuesday, 23 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Approved Counter and Signatory: [REDACTED]

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4299	Gate 3 North End Decon	700	1500 480 min	1.0	1/100	< 0.01
A27351-S4300	Gate 3 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4301	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4302	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4303	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4304	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4305	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4306	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4307	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4308	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4309	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4310	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4311	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R450
Client: Georgiou
Client Address: Level 3,
 53 Berry Street,
 North Sydney, NSW, 2060

Report Date: Tuesday, 30 April 2024
Analysed Date: Monday, 29 April 2024
Laboratory Receival Date: Monday, 29 April 2024
Sampled Date: Wednesday, 24 April 2024

Sampled By: [REDACTED]
Approved Counter and Signatory: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project
Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4312	Gate 3 North End	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4313	Gate 3 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4314	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4315	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4316	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4317	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4318	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4319	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4320	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4321	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4322	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4323	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4324	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT Estimation of Airborne Asbestos Fibres

Report No: A27351-R451
Client: Georgiou
Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Wednesday, 1 May 2024
Analysed Date: Wednesday, 1 May 2024
Laboratory Receival Date: Wednesday, 1 May 2024
Sampled Date: Monday, 29 April 2024

Sampled By: [REDACTED]

Attention: [REDACTED]
Sampled From: Parkes Bypass Project

Approved Counter and Signatory: [REDACTED]

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4325	Gate 3 North End Work Zone	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4326	Gate 3 Clean End Decon	700	1500 480 min	1.0	1/100	< 0.01
A27351-S4327	Gate 10 Fence	700	1500 480 min	1.0	1/100	< 0.01
A27351-S4328	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4329	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4330	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4331	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4332	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4333	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4334	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4335	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4336	Gate 8 Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4337	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT

Estimation of Airborne Asbestos Fibres

Report No: A27351-R452	Report Date: Wednesday, 1 May 2024
Client: Georgiou	Analysed Date: Wednesday, 1 May 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Wednesday, 1 May 2024
	Sampled Date: Tuesday, 30 April 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parkes Bypass Project	Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4338	Gate 3 North	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4339	Gate 3 Clean End Decon	700	1500 480 min	1.0	1/100	< 0.01
A27351-S4340	Gate 10 Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4341	Fill 5 Wheelwash Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4342	Cut 3 West Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4343	Cut 3 Condobolin Road	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4344	Cut 3 East Fence	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4345	Brolgan Road East	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4346	Brolgan Road West	700	1500 480 min	1.0	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A27351-S4347	Reedsdale Road North Adjacent Containment Cell	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4348	Gate 8 Clean End Decon	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4349	Gate 8 Clean Crib Room	700	1500 480 min	1.0	0/100	< 0.01
A27351-S4350	Quality Control Laboratory Blank	700	1500 480 min	N.A.	0/100	Acceptable limit

LABORATORY ANALYSIS REPORT Estimation of Airborne Asbestos Fibres

Report No: A31029-R2
Client: Georgiou
Client Address: Level 3,
53 Berry Street,
North Sydney, NSW, 2060

Report Date: Wednesday, 1 May 2024
Analysed Date: Wednesday, 1 May 2024
Laboratory Receival Date: Wednesday, 1 May 2024
Sampled Date: Monday, 29 April 2024

Sampled By: [REDACTED]

Approved Counter and Signatory: [REDACTED]

Attention: [REDACTED]
Sampled From: Parks Bypass project

Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A31029-S23	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S24	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S25	Ballardee Lane South/West	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S26	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S27	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S28	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S29	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S30	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S31	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A31029-S32	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S33	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S34	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S35	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S36	158 Goldrush Road South/East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S37	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S38	Cut 3 Reedsdale Road South/East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S39	Reedsdale Road / Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S40	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S41	125 Painters Street	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S42	Lot 1 Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S43	Lot 1 Bogan Road North/West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S44	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	< 0.01

LABORATORY ANALYSIS REPORT Estimation of Airborne Asbestos Fibres

Report No: A31029-R3	Report Date: Wednesday, 8 May 2024
Client: Georgiou	Analysed Date: Thursday, 2 May 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Thursday, 2 May 2024
	Sampled Date: Tuesday, 30 April 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parks Bypass project	Type of Monitoring: Background Monitoring During Earthworks
Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.	

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A31029-S45	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S46	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S47	Ballardee Lane South/West	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S48	Ballardee Lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S49	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S50	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S51	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S52	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S53	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A31029-S54	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S55	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S56	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S57	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S58	158 Goldrush Road South / East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S59	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S60	Cut 3 Reedsdale Road South/ East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S61	Reedsdale Road / Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S62	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S63	125 Painters Street	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S64	Lot 1 - Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S65	Lot 1 - Bogan Road North/ West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S66	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	< 0.01

LABORATORY ANALYSIS REPORT Estimation of Airborne Asbestos Fibres

Report No: A31029-R4	Report Date: Wednesday, 8 May 2024
Client: Georgiou	Analysed Date: Friday, 3 May 2024
Client Address: Level 3, 53 Berry Street, North Sydney, NSW, 2060	Laboratory Receival Date: Friday, 3 May 2024
	Sampled Date: Wednesday, 1 May 2024
	Sampled By: [REDACTED]
Attention: [REDACTED]	Approved Counter and Signatory: [REDACTED]
Sampled From: Parks Bypass project	Type of Monitoring: Background Monitoring During Earthworks

Test Method: In accordance with the NOHSC:3003 (2005) Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres (as outlined in the Laboratory Method Manual). Accredited for compliance with ISO/IEC:17025-Testing.

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A31029-S67	London Road South	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S68	London Road North	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S69	Ballardee lane South/ West	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S70	Ballardee lane North	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S71	Brolgan Road West	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S72	Brolgan Road East	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S73	Hartigan Avenue West	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S74	Hartigan Avenue East	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S75	Hartigan Avenue North	1159	1200 1440 min	0.5	0/100	< 0.01

Sample Number	Sample Location	Time		Flow Rate L/ Min	Results Fibres / Field	Results Fibres / ml
		On	Off			
A31029-S76	Cut 3 Moulden Street South	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S77	Cut 3 Moulden Street North	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S78	Fill 4 Moulden Street	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S79	Cut 3 Moulden Street West	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S80	158 Goldrush Road South/East Gate	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S81	163 Goldrush Road	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S82	Cut 3 Reedsdale Road South/East Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S83	Reedsdale Road /Thomas Street	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S84	Fill 4 Reedsdale Road	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S85	125 Painter Street	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S86	Lot 1 - Bogan Road West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S87	Lot 1 - Bogan Road North/ West Fence	1159	1200 1440 min	0.5	0/100	< 0.01
A31029-S88	Quality Control Laboratory Blank	1159	1200 1440 min	N.A.	0/100	< 0.01